

Garrett GT12 Type Turbos

Common Service Parts

GT12 Type

Common Service Parts

Illustration for this turbo is not currently available – please contact Melett Engineers for latest availability of technical information.

GT12 Type

Repair Parts & Service Kits

Key	Part Description	MELETT Number	Qty Per Turbo	Repair Kit
	Journal Bearing (Ramped Thrust Faces)	1102-012-100	1	1
	Piston Ring (Same T&C End)	1102-012-160	2	2
	Thrust Washer	N/A	1	

Oversize Repair Parts are not available for this turbo model.

Technical Note: Melett Engineers do not recommend the use of undersize bearings / shafts in the GT12 turbos.