

Garrett GT50 BTG UTV Type Turbos

Common Repair Parts

GT50 / BTG / TV85 Type

Component Parts Common

Illustration for this turbo is not currently available – please contact Melett Engineers for latest availability of technical information.

GT50 / BTG / UTV Type

Repair Parts & Service Kits

These models are currently under development in 2007 – please contact Melett Sales for latest availability.

The following parts are available from stock as shown.

GT50

Part Description	MELETT Part Number	OE Part Number	Qty Per Turbo
Journal Bearing Std/Std	1101-285-100	448508-0001	2
Piston Ring Turb End	1100-180-160	408049-0008	1

BTG / UTV / TV75/85

Part Description	MELETT Part Number	OE Part Number	Qty Per Turbo
Journal Bearing Std/Std	1101-285-100	448508-0001	2
Retaining Ring (J-Brg)	1100-180-140	400408-0000	3
Wear Washer	1100-180-190	407135-0000	2
O-Ring	1100-040-150	400424-0000	1
Piston Ring Turb End	1100-045-160	403818-0030	1
Piston Ring Turb End	1101-285-160	408049-0015	1
Piston Ring Comp End	1100-045-170	403818-0047	2
Shaft Nut	1100-180-350	400768-0013	1
			from OE kit 700468-0001

Note: Piston Ring 408049-0015 is dimensionally the same as the T18/GT50 piston ring 408049-0008 but is manufactured from higher temp M2 stainless. Make sure the correct ring is used as they are not backward interchangeable.