

Garrett GT30 / GT32 / GT35 Type Turbos

Common Service Parts

GT30/32/35 Type

Common Service Parts

Illustration for this turbo is not currently available – please contact Melett Engineers for latest availability of technical information.

GT30/32/35 Type

Repair Parts & Service Kits

Key	Part Description	Melett Number	Replace OE No.	Qty Per Turbo	Minor Kit	Major Kit
					1102-032-750	1102-032-751
	Journal Bearing Std/Std	1102-032-100	448283-0002	2	2	2
	O-Ring (Brg Hsg) Sq. Sec.	1102-032-150	400424-0010	1	1	1
	O-Ring (Comp Cover)	1102-032-155	403069-0077	1	1	1
	Piston Ring (Turb)	1102-032-160	408049-0013	1	1	1
	Piston Ring (Comp)	1102-032-170	403818-0009	1	1	1
	Thrust Collar GT32	1102-032-200	448845-0001	1		1
	Thrust Bearing (270 degree)	1102-032-320	448261-0001	1	1	1
	Oil Seal Washer (Doughty)	1102-032-580	449386-0001	1	4	4
	Bolt (C/Cover) Lock patch	1100-045-610	400724-0810	6	6	6
	Turbine Bolt (B16 UHT)	1102-040-620	447571-0820	8	8	8
	Clamp Plate	N/A	443136-0001	8		
	Bearing Spacer	N/A	447480-0002	2		
						Similar to... 709147-1

Oversize Repair Parts Available

Journal Bearings		
Original Garrett Part Number (Std/Std): 448283-0002		
Oversize's Available		Part Number
OD +.010"	ID -.010"	1102-032-120
OD +.010"	ID Std	1102-032-124
OD Std	ID -.010"	1102-032-127

Piston Rings	
Oversize's Available	Part Number
Turbine End	
Oversize Piston Rings are not available at time of printing – please contact Melett Sales for latest availability.	